



**DONGFENG**

**DFL1250A8-K01E-403-022J 3P S/C**  
**16T BOX ONDULE**  
**6X4 BVM DIES**











MOTORLAND

Vue de profil





MOTORLAND

Jante acier 11.00R20



A close-up photograph of the interior of a car door. The door panel is a light grey color with a textured surface. A black door handle is located in the upper left. Below it is a rectangular storage pocket. In the center, there is a black manual window crank. To the right of the crank is a small, dark, rectangular button or switch. The door is open, and the background shows a gravel surface and a person's leg in a white shoe.

MOTORLAND

Lève-vitre manuel



MOTORLAND

Levier de vitesse





MOTORLAND

Clé de démarrage





Tableau de bord





Tableau de bord





Volant uréthane





Cabine avec couchette arrière





MOTORLAND

Siège tissu





MOTORLAND

Vue arrière



MOTORLAND

Vue arrière